ILLINOIS ENVIRONMENTAL PROTECTION AGENCY 811 Solid Waste Landfill Inspection Checklist

	J		i vvusto i	Lulia	ор.			
County:	St. Clair	L	_PC#: 16	330755	017	_ Re	gion: <u>6 - Colli</u>	insville
Location/Sit	e Name: Mari	ssa/Cottor	wood Hills	RDF				
Date:	05/24/2012 Tim	e: From	9:00am	То	10:55am	Previous Inspecti	on Date: 01/06	6/2012
Inspector(s)	Description Site Name Marissa Cottonwood Hills RDF						s F.	
No. of Photo	Marissa/Cottonwood Hills RDF						No 🗵	
Interviewed	Description Description					<u> </u>		
Permitted C	Owner Mailing Ad	dress			Permitt	ed Operator Mailin	g Address	
Waste Man	nagement of Illino	is Inc.			Waste	—— Management of Illir	nois Inc.	
	_				· i	•		
		ı				• • • • • • • • • • • • • • • • • • • •		
	·						Address EC	EIVED
					- 1			<u></u>
1	•						JUN	2 7 2012
					1		n1	1 / D 🖳 B
manioca,	11013 0220.					· her bing iiiiraia a		
	ZATION:	OPE	RATIONAL	STAT	`` TIS:	TYPE OF (OPERATION:	
		-		****			ls 814-Subp	
				ified.			814-Subp	
Latest Mo	od. 45	Close	ed-Date Ce	rtified:		New Landfill	ls: 811-Putre	es./Chem. 🛚 🖾
Exp Date .	07/15/2014							
							···	
	SECTION				DESCRIP	TION		VIOL
	ILLINOIS	S ENVIRO	NMENTA	L PRC	TECTION	N ACT REQUIRE	MENTS	
1.								
2.	 	CAUSE C	OR ALLOW	OPEN E	BURNING			
<u> </u>	12(a)						ILLINOIS	
4.	12(d)							
	40/5		THREATEN ON OF AN N			HARGE WITHOUT	OR IN	
<u>5.</u> 6.	12(f) 21(a)	+	OR ALLOW ($+$ \neg
<u> </u>	21(0)	+				ASTE-TREATMENT	OR WASTE- D	ISPOSAL

DISPOSAL OPERATION WITHOUT A RCRA PERMIT. IFPA-DMISION OF RECORDS MANAGEMENT RELEASABLE

AUG 1 5 2012

Revised 10/20/2009

8.

9.

21(d)

21(e)

21(f)(1)

(1)

(2)

OPERATION:

Provisions)

(811 Solid Waste-1)

Without a Permit or in Violation of Any Conditions of a Permit (See Permit

In Violation of Any Regulations or Standards Adopted by the Board DISPOSE, TREAT, STORE, OR ABANDON ANY WASTE, OR

TRANSPORT ANY WASTE INTO THE STATE AT/TO SITES NOT MEETING REQUIREMENTS OF ACT AND REGULATIONS

CONDUCT ANY HAZARDOUS WASTE-STORAGE, TREATMENT OR

REVIEWER MED

LPC #: 1630755017

Inspection Date: 05/24/2012

10.	21(o)	CONDUCT A SANITARY LANDFILL OPERATION WHICH RESULTS IN ANY FOLLOWING CONDITIONS:	OF THE
	(1)	Refuse in Standing or Flowing Water	
	(2)	Leachate Flows Entering Waters of the State	
	(3)	Leachate Flows Exiting the Landfill Confines	
	(4)	Open Burning of Refuse in Violation of Section 9 of the Act	
	(5)	Uncovered Refuse Remaining From Any Previous Operating Day or at the Conclusion of Any Operating Day	
	(6)	Failure to Provide Final Cover Within Time Limits	
	(7)	Acceptance of Wastes Without Necessary Permits	
	(8)	Scavenging as Defined by Board Regulations	
	(9)	Deposition of Refuse in Any Unpermitted Portion of the Landfill	1 -
	(10)	Acceptance of Special Waste Without a Required Manifest	
	(11)	Failure to Submit Reports Required by Permits or Board Regulations	
	(12)	Failure to Collect and Contain Litter by the End of each Operating Day	
	(13)	Failure to Submit Any Cost Estimate, Performance Bond or Other Security	
11.	21(t)	CAUSE OR ALLOW A LATERAL EXPANSION OF A MUNICIPAL SOLID WASTE LANDFILL (MSWLF) UNIT WITHOUT A PERMIT MODIFICATION.	
12.	21.6(b)	ACCEPTANCE OF LIQUID USED OIL FOR FINAL DISPOSAL (EFFECTIVE JULY 1, 1996)	
3.	22.01	FAILURE TO SUBMIT ANNUAL NONHAZARDOUS SPECIAL WASTE	
14.	22.17	LANDFILL POST-CLOSURE CARE	
	(a)	Failure to Monitor Gas, Water, Settling	
	(b)	Failure to Take Remedial Action	
15.	22.22(c)	ACCEPTANCE OF LANDSCAPE WASTE FOR FINAL DISPOSAL	
16.	22.23(f)(2)	CAUSE OR ALLOW THE DISPOSAL OF ANY LEAD-ACID BATTERY	├ ──
17.	22.28(b)	ACCEPTANCE OF WHITE GOODS FOR FINAL DISPOSAL	
18.	55(b)(1)	ACCEPTANCE OF ANY USED OR WASTE TIRE FOR FINAL DISPOSAL (UNLESS LANDFILL MEETS EXEMPTION OF 55(b)(1))	
19.	55(k)	NO PERSON SHALL:	
	(1)	Cause or Allow Water to Accumulate in Used or Waste Tires	
	(4)	Transport Used or Waste Tires in Violation of the Registration and Placarding Requirements	
20.	56.1(a)	CAUSE OR ALLOW THE DISPOSAL OF ANY POTENTIALLY INFECTIOUS MEDICAL WASTE	
,	SOLID V	VASTE SITE OPERATOR CERTIFICATION LAW REQUIREMENTS	
21.	225 ILCS 230/1004	CAUSING OF ALLOWING OPERATION OF A LANDFILL WITHOUT PROPER COMPETENCY CERTIFICATE	
		35 ILLINOIS ADMINISTRATIVE CODE REQUIREMENTS SUBTITLE G	
		PRIOR CONDUCT CERTIFICATION REQUIREMENTS	

Revised 10/20/2009

(811 Solid Waste-2)

LPC #: 1630755017 Inspection Date: 05/24/2012

	 		
22.	745.181	CHIEF OPERATOR REQUIREMENTS	
23.	745.201	PRIOR CONDUCT CERTIFICATION PROHIBITIONS	
	-	SPECIAL WASTE HAULING REQUIREMENTS	
24.	809.301	REQUIREMENTS FOR DELIVERY OF SPECIAL WASTE TO HAULERS	
	-		
25.	809.302(a)	REQUIREMENTS FOR ACCEPTANCE OF SPECIAL WASTE FROM HAULERS	
26.	809.501	MANIFESTS, RECORDS, ACCESS TO RECORDS, REPORTING REQUIREMINAND FORMS	ENTS
	(a)	Delivery of Special Waste to Hauler	
	(g)	Retention of Special Waste Manifests	
	1	NEW SOLID WASTE LANDFILL REQUIREMENTS	
	PART 811		
	SUBPART	GENERAL STANDARDS FOR ALL LANDFILLS	·
27.	811.103	SURFACE WATER DRAINAGE	
	(a)	Runoff from Disturbed Areas	
	(b)	Diversion of Runoff from Undisturbed Areas	
28.	811.104	SURVEY CONTROL	<u> </u>
	(a)	Boundaries Surveyed and Marked	
	(b)	Stakes and Monuments Marked	
	(c)	Stakes and Monuments Inspected	
	(d)	Control Monument Established and Maintained	
29.	811.105	COMPACTION	
	244.400	DAN WAGNED	
30.	811.106	DAILY COVER Six Inches Soil	[]
:	(a)	Alternative Daily Cover	
	(b)	Allerhative Daily Cover	
31.	811.107	OPERATING STANDARDS	
	(a)	Phasing of Operations	
	(b)	Work Face Size and Slope	
	(c)	Equipment	
	(d)	Utilities	
	(e)	Maintenance	
	(f)	Open Burning	
	(g)	Dust Control	
	(h)	Noise Control	
	(i)	Vector Control	
	(i)	Fire Protection	
	(k)	Litter Control	
	(i)	Mud Tracking	
	(m)	Liquid Restrictions for MSWLF Units	
32.	811.108	SALVAGING	

Revised 10/20/2009

(811 Solid Waste-3)

LPC #: 1630755017

Inspection Date: 05/24/2012

	<u> </u>	Salvaging Interfered with Operation	· 1
	(a)	Salvaging Interferes with Operation	
	(b)	Safe and Sanitary Manner	
	(c)	Management of Salvagable Materials	
33.	811.109	BOUNDARY CONTROL	
	(a)	Access Restricted	
	(b)	Proper Sign Posted	
34.	811.110	CLOSURE AND WRITTEN CLOSURE PLAN	
	(a)	Final Slopes and Contours	
	(b)	Drainage Ways and Swales	
	(c)	Final Configuration	十 清
	(d)	Written Closure Plan	
	(e)	Initiation of Closure Activities at MSWLF Units	
	(f)	Completion of Closure Activities at MSWLF Units	
_	(g)	Deed Notation for MSWLF Units	
35.	811.111	POST-CLOSURE MAINTENANCE	<u> </u>
<u> </u>	(a)	Procedures After Receipt of Final Volume of Waste	<u> </u>
	(b)	Remove All Equipment of Structures	+ =
	(c)	Maintenance and Inspection of the Final Cover and Vegetation	
	(d)	Planned Uses of Property at MSWLF Units	 -<u>:</u>-
	(u)	Training Good of Fragory action that	
36.	811.112	RECORDKEEPING REQUIREMENTS FOR MSWLF UNITS	1
	(a)	Location Restriction Demonstration	
	(b)	Load Checking Requirements	
	(c)	Gas Monitoring Records	
	(d)	MSWLF Liquid Restriction Records	
	(e)	Groundwater Monitoring Program Requirements	
	(f)	Closure and Post Closure Care Requirements	
	(g)	Cost Estimates and Financial Assurance Requirements	
	PART 811 SUBPART C	PUTRESCIBLE AND CHEMICAL WASTE LANDFILLS	
37.	811.302	FACILITY LOCATION	··
	(c)	Site Screening (Does Not Apply To Part 814-Subpart D Sites)	
38.	811.309	LEACHATE TREATMENT AND DISPOSAL SYSTEM	
	(a)	General Requirements	
	1 1-1		+=-
	(c)	Standards for On-Site Treatment and Pretreatment	
	(c) (d)	Standards for On-Site Treatment and Pretreatment Standards for Leachate Storage System	
	(d)		
	(d) (e)	Standards for Leachate Storage System	
	(d)	Standards for Leachate Storage System Standards for Discharge to Off-Site Treatment	
39	(d) (e) (f) (g)	Standards for Leachate Storage System Standards for Discharge to Off-Site Treatment Standards for Leachate Recycling Systems Standards for Leachate Monitoring Systems	
39.	(d) (e) (f) (g) 811.310	Standards for Leachate Storage System Standards for Discharge to Off-Site Treatment Standards for Leachate Recycling Systems Standards for Leachate Monitoring Systems LANDFILL GAS MONITORING (FOR SITES ACCEPTING PUTRESCIBLE WARDS)	
39.	(d) (e) (f) (g)	Standards for Leachate Storage System Standards for Discharge to Off-Site Treatment Standards for Leachate Recycling Systems Standards for Leachate Monitoring Systems	

Revised 10/20/2009

(811 Solid Waste-4)

LPC #: 1630755017 Inspection Date: 05/24/2012

40.	811.311	LANDFILL GAS MANAGEMENT SYSTEM (FOR CHEMICAL AND PUTRES LANDFILLS)	VIDLE
40.	_	Conditions for Installation of Gas Management System	
	(a)	Notification and Implementation Requirements	ᆉ
	(b)	Standards for Gas Venting	+
	(c)	Standards for Gas Collection	-
	(d)	Standards for Gas Collection	
41.	811.312	LANDFILL GAS PROCESS AND DISPOSAL SYSTEM	
	(c)	No Unpermitted Gas Discharge	<u> </u>
	(d)	Gas Flow Rate Measurements into Treatment of Combustion Device	
	(e)	Standards for Gas Flares	_
	(f)	Standards for On-Site Combustion of Landfill Gas Using Devices Other Than	
	(g)	Flares Gas Transported Off-Site	
	i.		
42.	811.313	INTERMEDIATE COVER Requirements for the Application for Intermediate Cover	
	(a)	Runoff and Infiltration Control	
	(b)		- - -
	(c)	Maintenance of Intermediate Cover	
43.	811.314	FINAL COVER SYSTEM (DOES NOT APPLY TO PART 814 SITES THAT H. CLOSED, COVERED AND VEGETATED PRIOR TO SEPTEMBER 18, 1990	AVE
	(a)	General Requirements	
	(b)	Standards for Low Permeability Layer	
	(c)	Standards for Final Protective Layer	
44.	811.316	PLUGGING AND SEALING OF DRILL HOLES	
45.	811.321	WASTE PLACEMENT	
	(a)	Phasing of Operations	
	(b)	Initial Waste Placement	
46.	811.322	FINAL SLOPE AND STABILIZATION	
40.		Grade Capable of Supporting Vegetation and Minimizing Erosion	
	(a)	Slopes Required to Drain	
	(b)	Vegetation	
	(c)	Structures Built over the Unit	╅┾
	(d)	Structures built over the Onit	<u>.] </u>
47.	811.323	LOAD CHECKING PROGRAM	
	(a)	Load Checking Program Implemented	<u> </u>
_	(b)	Load Checking Program for PCB's at MSWLF Units	
	(c)	Load Checking Program Components	
	(d)	Handling Regulated Hazardous Wastes	
	PART 811 SUBPART D	MANAGEMENT OF SPECIAL WASTES AT LANDFILLS	
48.	811.402	NOTICE TO GENERATORS AND TRANSPORTERS	
	811.403	SPECIAL WASTE MANIFESTS REQUIREMENTS	
<u>49.</u>	011.400	Of Edine Who I with the control of t	

Revised 10/20/2009

(811 Solid Waste-5)

LPC #: 1630755017

Inspection Date: 05/24/2012

	(a)	Special Waste Profile Identification Sheet	
	(b)	Special Waste Recertification	
51.	811.405	RECORDKEEPING REQUIREMENTS	
52.	811.406	PROCEDURES FOR EXCLUDING REGULATED HAZARDOUS WASTES	
	PART 811 SUBPART G	FINANCIAL ASSURANCE	
53.	811.700	COMPLY WITH FINANCIAL ASSURANCE REQUIREMENTS OF PART 811, SUBPART G	
54.	811.701	UPGRADING FINANCIAL ASSURANCE	
55.	811.704	CLOSURE AND POST-CLOSURE CARE COST ESTIMATES	
56.	811.705	REVISION OF COST ESTIMATE	
		SOLID WASTE FEE SYSTEM REQUIREMENTS	
57.	Part 858 Subpart B	MAINTAINED, RETAINED & SUBMITTED DAILY & MONTHLY SOLID WASTE RECORDS AND QUARTERLY SOLID WASTE SUMMARIES WHERE INCOMING WASTE IS WEIGHED (LIST SPECIFIC SECTION	
58.	Part 858 Subpart C	MAINTAINED, RETAINED & SUBMITTED DAILY & MONTHLY SOLID WASTE RECORDS AND QUARTERLY SOLID WASTE SUMMARIES WHERE INCOMING WASTE IS NOT WEIGHED (LIST SPECIFIC	
	,	OTHER REQUIREMENTS	
59.	OTHER:	APPARENT VIOLATION OF: ([]) PCB; ([]) CIRCUIT COURT CASE NUMBER: ORDER ENTERED ON:	
60.			

Informational Notes

- 1. [Illinois] Environmental Protection Act: 415 ILCS 5/4.
- 2. Illinois Pollution Control Board: 35 III. Adm. Code, Subtitle G.
- 3. Statutory and regulatory references herein are provided for convenience only and should not be construed as legal conclusions of the Agency or as limiting the Agency's statutory or regulatory powers. Requirements of some statutes and regulations cited are in summary format. Full text of requirements can be found in references listed in 1. and 2. above.
- 4. The provisions of subsection (o) of Section 21 and subsection (k) of Section 55 of the [Illinois] Environmental Protection Act shall be enforceable either by administrative citation under Section 31.1 of the Act or by complaint under Section 31 of the Act.
- 5. This inspection was conducted in accordance with Sections 4(c) and 4(d) of the [Illinois] Environmental Protection Act: 415 ILCS 5/4(c) and (d).
- 6. Items marked with an "NE" were not evaluated at the time of this inspection.

Revised 10/20/2009

(811 Solid Waste-6)

LPC #: 1630755017

Inspection Date: 05/24/2012

	PERMIT PROVISIONS
PERMIT NUMBER	DESCRIPTION OF VIOLATION (condition # of permit, page # of permit, and/or page # of approved application)
-	
,	
-	

Revised 10/20/2009

(811 Solid Waste-7)

LPC#-1630755017-St. Clair County Marissa/Cottonwood Hills RDF Inspectors: Kendall Couch

Page #1

Narrative.

RECEIVED

JUN 27 2012

IEPA/BOL

General Remarks

On May 24, 2012, I went to Marissa, Illinois to perform an inspection at this site. This site is an IEPA permitted landfill operating under permit number 1998-110-LF Mod. #45. The weather was sunny, dry, windy and 75° Fahrenheit when I arrived at 9:00am. The hours of operation for this facility are 4:00am to 4:00pm Monday through Friday.

Inspection

As I arrived at this facility I took a picture (#1) of the entrance sign. Several signs are at the entrance and scalehouse. These signs appear to adequetely comply with applicable regulations. The roads entering this facility appeared relatively clean and free of tracking mud. I then met with Lesley Foertsch, Scalehouse Manager for Waste Management. Ms. Foertsch estimated an average of 2100 to 2200 tons of incoming waste per day. Ms. Foertsch radioed Bill Raynor, Certified Operator of this site. Mr. Raynor subsequently arrived at the scalehouse and we began this inspection by driving to the active face located in the new cell, Phase III Northeast. I took four pictures (#2-5) of the active face. The new cell was comprised of two levels with the upper level approximately 10 to 15 feet below the top of the cell liner. Picture #2 depicts the waste level on the northeast end of the new cell.

The lower level contained the tipper and active area. Active area was approximately 1000 square yards in size. I watch as several trucks dumped their load and inspected the active face from the upper portion of this area. No unpermitted waste was observed except for several tires already removed from the waste and staged from removal. The trash trucks observed were tarped as required. The equipment on site was an 836 Caterpillar Compactor, 700 Caterpillar Dozer and other heavy equipment performing excavation work for future adjacent cell development. The active face personnel were Joe Jabron, Mike Burrus and Kerry Daugherty. Some litter was observed on the southern sideslope of Phase III Northwest. Two litter pickers were on-site during this inspection containing this blown litter. A water truck was also operational to control fugitive dust.

After inspecting the active area we drove around the landfill and observed the northeastern and western side slopes. Some repair work had been done towards the northern portion of the landfill and final cover work continued on the southeast sideslope. Five acres of final cover will be completed within the near future. Hurst-Rosche was at this facility performing survey work for the final cover and checking the monuments for visual capability.

> IEPA - DIVISION OF RECORDS MANAGEMENT RELEASABLE

> > AUG 1 5 2012

REVIEWER MED

Mr. Raynor stated that the gas well system appears to be working properly. I asked Mr. Raynor about the down time for the gas flare in November 2011 that was documented in Cottonwood Hill's annual report. The flare was down for a total of 95.3 hours in November. Mr. Raynor believes that electrical spikes from the new Prairie State Power Plant during start-up operations caused the flare to go out. Mr. Raynor went on to say that the flare had been working normally since November 2011.

Three dumpsters were observed within the citizen's drop-off area as well as a recycling dumpster for recyclable materials. This area appeared clean and rock crushing operations had recently started back up as excavation work has generated new aggregate material for road base. It appears that the leachate pump stations are keeping the leachate liner levels within regulatory limits. Leachate sump, L302, was in the range the range of 18-23 inches. During our time on the southern end of the landfill we met Rick Schmidt of TekLab. Mr. Schmidt was sampling ground water well R311 for pesticide analysis. Mr. Schmidt stated that the GW wells appeared to be in good working order. Mr. Raynor stated that the solidification unit was back at Milam Landfill. It appears that Milam Landfill solidified as much waste as their permit allowed and the unit was brought to Cottonwood Hills in November 2011 until February 2012 to continue the solidification of liquid waste.

We then went to Mr. Raynor's office and service garage where I observed several methane monitors along with a number of fire extinguishers with unexpired tags. The tire dumpster was empty and covered as required. A used oil tank was also observed and properly labeled. Before leaving this landfill, I stopped just outside the gate to see if odors were leaving the landfill property. No odors were encountered at this location or on my way into Marissa. I went to the Marissa WWTP to ask if any odor complaints had been received. No one was present and I subsequently returned to the IEPA Collinsville Regional Office.

On June 6, 2012, I returned to this site to review required documentation of the day to day operations at this facility. The weekly load checking documentation appeared to be in order except for a few instances where the driver of the vehicle did not print his or her name. I instructed Mr. Raynor to fill out the waste checking logs completely as required. Mr. Raynor assured me that he would have his active face crew complete the logs sheets completely in the future. The ADC log documented the used of tarps and soil used for daily cover. The daily operating record documented the placement of deodorizers at the WWTP to help with leachate odors leaving the WWTP grounds. A leachate sump pumped had been replaced at the L302 pumping station. Mr. Raynor explained that the new leachate pump quality control measures had been working well and this pump was replaced within several days. Back-up pumps have been placed at this facility for future break downs.

I reviewed the solidification documentation. It appears that all the liquid waste brought into this facility was profiled into the landfill through Waste Management's special waste unit located at the Milam Landfill and or Wisconsin. It appears the main waste streams solidified at this facility were components of Dial Soap and oily water from Illini Environmental of Caseyville, Illinois. It appears that the absorbent used at this facility was soil or flyash. I also reviewed several special waste stream profile documentation.

On June 7th and 21st, 2012, I returned to this site to double check several solidification and special waste records due to questions generated during the documentation review on June 6th. Manifest documenting the solidification waste streams and Illinois MPP metal Hydroxide Sludge were reviewed. After this review, it appears that the documentation complies with the applicable regulations. No violations will be noted.

cc: DLPC/FOS -Collinsville Regional

STATE OF ILLINOIS ENVIRONMENTAL PROTECTION AGENCY SITE SKETCH

Date of Inspection: May 24, 2012

BOL ID No.: 1630755017

Site Name: Cottonwood Hills RDF

Inspector: Kendall Couch


County: St. Clair

Time: 9:00am-10:55am

Measurements Approximate


North /

Direction of Photo





DIGITAL PHOTOGRAPHS File Names: 1630755017-05242012-[Exp. #1-2].jpg



Date: 05/24/2012
Time: 9:00am-10:55am
Direction: West
Photo by: K. Couch
Exposure #: 001
Comments: Entrance
Sign.




Date: 05/24/2012 Time: 9:00am-10:55am Direction: Northeast Photo by: K. Couch Exposure #: 002

Comments: Top of New


Cell.

DIGITAL PHOTOGRAPHS

File Names: 1630755017 -05242012-[Exp. #3-4].jpg



Date: 05/24/2012
Time: 9:00am-10:55am
Direction: West
Photo by: K. Couch
Exposure #: 003
Comments: East Slope
of Phase 3NW.



Date: 05/24/2012 Time: 9:00am-10:55am Direction: Southwest Photo by: K. Couch Exposure #: 004 Comments: Active Face in Southwestern Part of

Phase 3NE.

Page 2 of 5



DIGITAL PHOTOGRAPHS File Names: 1630755017-05242012-[Exp. #5-6].jpg



Date: 05/24/2012 Time: 9:00am-10:55am Direction: South Photo by: K. Couch Exposure #: 005 Comments: Active


Face.



Date: 05/24/2012 Time: 9:00am-10:55am Direction: Down Photo by: K. Couch Exposure #: 006 Comments: Property

Survey Marker.

DIGITAL PHOTOGRAPHS File Names: 1630755017-05242012-[Exp. #7-8].jpg



Date: 05/24/2012 Time: 9:00am-10:55am

Direction:

Photo by: K. Couch Exposure #: 007 Comments: Methane Gas Monitor.



Date: 05/24/2012 Time: 9:00am-10:55am

Direction:

Photo by: K. Couch Exposure #: 008 Comments: Fire Extinguisher.




DIGITAL PHOTOGRAPHS

File Names: 1630755017~05242012-[Exp. #9-10].jpg



Date: 05/24/2012 Time: 9:00am-10:55am Direction: West Photo by: K. Couch Exposure #: 009 Comments: Dust Suppression Activity.



Date: 05/24/2012 Time: 9:00am-10:55am

Direction:

Photo by: K. Couch Exposure #: 010 Comments: Used Oil

Reservoir.

SOLIDIFICATION INFORMATION

DATE	PROFILE#	MANIFEST	WASTE NAME	GALLONS	GENERATOR NAME, ADDRESS, CITY, STATE, ZIP	HAULER & ID	GENERATOR ID	REAGNET OR ABSORBENT	PA PA FIL
1/3/2012	IF1002105S	8853076	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999		YES
					6201 McKISSOCK	5108			
					ST LOUIS, MO 63147				
1/3/2012	108438IL	9150243	OILY WATER	5000	ILLINI ENVIRONMENTAL	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
					CASEYVILLE, IL 62232				
1/3/2012	108438IL	9150209	OILY WATER	2775	ILLINI ENVIRONMENTAL	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
<u> </u>					CASEYVILLE, IL 62232				
1/3/2012	108438IL	9150208	OILY WATER	2800	ILLINI ENVIRONMENTAL	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
	-			ļ	CASEYVILLE, IL 62232]
1/3/2012	108438IL	9150251	OILY WATER	5000	ILLINI ENVIRONMENTAL	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
					CASEYVILLE, IL 62232				
1/4/2012	IF1002105S	8853077	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
		1			6201 MCKISSOCK	5108			1
					ST LOUIS, MO 63147			<u> </u>	
1/4/2012	111531IL	8853035	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6901 MCKISSOCK	5108			
		<u> -</u>		<u></u>	ST LOUIS, MO 63147				
1/4/2012	108438IL	9150211	OILY WATER	4375		ILLINI	ILR000107086	FLY ASH	YES
				1		UPW103665-IL	Į.	!	
. /2 /2 2				ļ	CASEYVILLE, IL 62232				
1/5/2012	IF1002105S	8853084	SURFACTANT	3000		IPS	9290019999	FLY ASH	YES
		1		1	6201 MCKISSOCK	5108	;		1
4/5/2042	400400#			ļ <u>.</u>	ST LOUIS, MO 63147	·			
1/5/2012	108438IL	9150250	OILY WATER	2750	ILLINI ENVIRONMENTAL, INC		ILR000107086	FLY ASH	YES
	1					UPW103665-IL			1
1/5/2022	4004200	0450015			CASEYVILLE, IL 62232				
1/5/2012	108438/L	9150212	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	i .	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
1/5/2012	1115210	0052027	2018	 	CASEYVILLE, IL 62232				
1/5/2012	111531IL	8853037	SOAP	3000	I.	IPS	9290019999	FLY ASH	YES
	1	1			6901 MCKISSOCK	5108	3		

1/5/2012	10020211	744000	011111111111111111111111111111111111111		ST LOUIS, MO 63147	1630755017			i
1/5/2012	109282IL	/119324	OIL WATER		THE KIESEL COMPANY	THE KIESEL CO.	9291897488	FLY ASH	YES
ł			EMULSION	:	#1 BRANCH ST.	UMPQ7715IL			
		<u>.</u> .			ST LOUIS, MO 63147				
1/5/2012	11153116	8853036	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6901 MCKISSOCK	5108			
					ST LOUIS, MO 63147				
1/5/2012	108438IL	9150242	OILY WATER	2825	ILLINI ENVIRONMENTAL, INC.	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
					CASEYVILLE, IL 62232				<u> </u>
1/5/2012	108438IL	9150245	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC.	ILLINI	ILR000107086	FLY ASH	YES
			[8895 CALIFORNIA DRIVE	UPW103665-IL		121 7311	
					CASEYVILLE, IL 62232				
1/5/2012	108438IL	9150244	OILY WATER	2900	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL		7.27 7.371	''-
				CASEYVILLE, IL 62232					
1/5/2012	109282IL	7119325	OIL WATER		THE KIESEL COMPANY	THE KIESEL CO.	9291897488	FLY ΔSH	YES
		EMULSION		#1 BRANCH ST.	UMPQ7715IL	0232037400	7 C1 7/3/1	''-	
				ST. LOUIS, MO 63147	2.7.25.0			1	
1/6/2012	111531IL	8853001	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YE:
1	İ	i			6901 MCKISSOCK	5108		1 61 7511	115.
					ST LOUIS, MO 63147				
1/6/2012	108438IL	9150246	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
•		,			8895 CALIFORNIA DRIVE	UPW103665-IL		1 21 71311	'``
				,	CASEYVILLE, IL 62232				
1/9/2012	108438IL	9150327	OILY WATER		ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
]					8895 CALIFORNIA DRIVE	UPW103665-IL			'-`
_					CASEYVILLE, IL 62232				ŀ
1/9/2012	108438IL	9150326	OILY WATER		ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
					l ·	UPW103665-IL	12.100107000	1 61 7311	
					CASEYVILLE, IL 62232				İ
/10/2012	108438IL	9150330	OILY WATER		ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YE
					8895 CALIFORNIA DRIVE	UPW103665-IL	121100107080	Ire: Asn	
					CASEYVILLE, IL 62232	0. 11105005 12			
/10/2012	IF1002105S	8853078	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	ELV VCH	YES
					6201 MCKISSOCK	5108		l Cr Ash	1,5
			<u> </u>		ST LOUIS, MO 63147			!	Ì
1/10/2012	108438IL	9150210	OILY WATER	3597	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
	İ				8895 CALIFORNIA DRIVE	UPW103665-IL		I LI ASH	1163
					CASEYVILLE, IL 62232			1	

1/10/2012	10843811	0150220	OILY WATER	2050	H				
', 10, 2012		9130326	OILT WATER		ILLINI ENVIRONMENTAL, INC		ILR00107086	FLY ASH	YES
						UPW103665-IL			
1/11/2012	11152111	0052002	5048		CASEYVILLE, IL 62232				
1/11/2012	1112211	8853002	SUAP			IPS	9290019999	FLY ASH	YES
			ļ	1	6901 McKISSOCK	5	108		1
4 (4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4					ST. LOUIS, MO 63147				
1/11/2012	108438IL	9150247	OILY WATER	2520	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107085	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL	i		
					CASEYVILLE, IL 62232				
1/12/2012	108143IL	8853016	TINOPAL UNPA	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
	1		SLURY		6901 McKISSOCK	5	108		1,23
_				1,	ST. LOUIS, MO 63147				
1/12/2012	111531IL	8853012	SOAP			IPS	9290019999	FLY ASH	YES
			İ		6901 McKISSOCK	5	108		1.23
					ST. LOUIS, MO 63147	J			
1/12/2012	108438IL	9150248	OILY WATER		ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
	į					UPW103665-IL	1211000107000	1 21 7311	163
		ļ.		CASEYVILLE, IL 62232					
1/12/2012	109282IL	7059468	OIL WATER		THE KIESEL COMPANY	THE KIESEL CO	 	FLY ASH	YES
					#1 BRANCH ST	UMP07715-IL	9291897488	h .	1163
				i i	ST. LOUIS, MO 63147	01411 07713 16	3231637466		
1/12/2012	108438IL	9150101	OILY WATER		ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL	1000107080	I CLI ASH	1163
					CASEYVILLE, IL 62232				
1/12/2012	108438IL	9150331	OILY WATER		ILLINI ENVIRONMENTAL, INC	IELINII	ILR000107086	CLV ACU	- 1
					8895 CALIFORNIA DRIVE	UPW103665-IL	ILEKONOTOVOSO	FLY ASH	YES
				1	CASEYVILLE, IL 62232	DF W103003-IL			
1/12/2012	108438IL	9150332	OILY WATER		ILLINI ENVIRONMENTAL, INC	II I IND	U 0000107006	ELV ACI	- 1
<i>'</i>					8895 CALIFORNIA DRIVE	UPW103665-IL	ILR000107086	FLY ASH	YES
					CASEYVILLE, IL 62232	OLAA102002-10			
1/13/2012	IF1002105S	8853079	SURFACTANT		DIAL CORPORATION	IDC		<u> </u>	
_, _0, _0	10021033	0033073	JONI ACTAINT			IPS _	9290019999	FLY ASH	YES
					6201 McKISSOCK	5	5108		:
1/13/2012	10843811	9150220	OILY WATER		ST. LOUIS, MO 63147				
+/ 13/ 2012	10043010	3130329	OILT WATER		ILLINI ENVIRONMENTAL, INC		ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	ENFIVORNMENTAL		ŀ	
1/13/2012	if1002105s	8853000	surfactant		CASEYVILLE, IL 62232	UPW103665-IL		<u> </u>	
-, -0; 2012	110021033	0022000	poriaciant		DIAL CORPORATION	IPS			
					6201 McKISSOCK	9	9290019999	FLY ASH	YES
1/12/2012	QM8800180	2466073	CADMACHER		ST. LOUIS, MO 63147				
1/12/2012	IMMOOODIAD	34660/3	CAR WASH SLUDG	250	UPS	EVAC	31559	FLY ASH	YES

	•				117 LARCEL	MPR000007765	I		İ
					SIKESTON, MO 63801				
1/13/2012 QM8800180	QM8800180	3466072	CAR WASH SLUDG	125	UPS	EVAC	15658	FLY ASH	YES
				1004 S BROADWAY	MOR000007815	-			
					POPOLAR BLUFF, MO 63901				
1/13/2012 QM8800180	3466075	CAR WASH SLUDG	100		EVAC	15657	FLY ASH	YES	
					3390 CO RD 361	MOR000007690			
					PALMAZRA, MO 63461				
1/13/2012	QM8800180	3466076	CAR WASH SLUDG	100		EVAC	15650	FLY ASH	YES
ļ	1	,			1411 BUS HWY 54	MOR000007682			'
					BOWLING GREEN, MO 63334				
1/13/2012	QM8800180	3466071	CAR WASH SLUDG	50	UPS	EVAC	15653	FLY ASH	YES
					101 GETTING LOVE	MOR000007864			1.50
					HAYDIG, MO 63851				
1/13/2012	QM8800180	8808785	CAR WASH SLUDG		UPS	EVAC	15652	FLY ASH	YES
			Ì		3425 WILLOW RD	MOR000007724			
					SCOTT CITY, MO 63780				ŀ
1/13/2012 QM8800180 88	8808786	CAR WASH SLUDG	225	UPS	EVAC	15662	FLY ASH	YES	
				60 INDUSTRIAL DR	MOR000007872			'	
		<u></u>		FARMINGTON, MO 63640					
1/13/2012	QM8800180	3466074	CAR WASH SLUDG	225	UPS	EVAC	4966	FLY ASH	YES
					20 GOODWING	MOD985798651			1
			ļ	1	CRYSTAL CITY, FESTUS, MO 6	•			ļ
1/16/2012	108438IL	9150303	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
			١ .		8895 CALIFORNIA DRIVE	UPW10365-IL			
					CASEYVILLE, IL 62232				
1/16/2012	IF1002105S	8853081	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
]				6201 MCKISSOCK	5108			1.2
					ST LOUIS, MO 63147				
1/16/2012	108438IL	9150305	OILY WATER	3705	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW10365-IL			'
					CASEYVILLE, IL 62232				
1/16/2012	108438IL	9150304	OILY WATER	2750	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
			!		8895 CALIFORNIA DRIVE	UPW10365-IL			'-
					CASEYVILLE, IL 62232				ļ
1/16/2012	IF1002105S	8853082	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6201 MCKISSOCK	5108			['-
		-			ST LOUIS, MO 63147				
1/16/2012 1084381	108438IL	9150140	OILY WATER	5000	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
•	1		1		8895 CALIFORNIA DRIVE			1	

					CASEYVILLE, IL 62232		1		į
1/16/2012	1084381L	9150139	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW10365-IL			1.23
					CASEYVILLE, IL 62232		:		
1/17/2012	IF1002105S	8853083	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
	\$				6201 McKISSOCK	5108			
				_	ST LOUIS, MO 63147				
l/17/2012	IF1002105S	8853085	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6201 McKISSOCK	5108			,
					ST LOUIS, MO 63147				Ì
1/17/2012	111531IL	8853011	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6901 McKISSOCK	5108			1,5
					ST LOUIS, MO 63147				
1/18/2012	108143IL	8853086	SURFACTANT	1500	DIAL CORPORATION	1PS	9290019999	FLY ASH	YES
					6201 McKISSOCK	5108			1.23
					ST. LOUIS, MO 63147				
1/18/2012	111531IL	8853010	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
				6901 McKISSOCK	5108				
				ST. LOUIS, MO 63147	,				
1/18/2012	108438IL	9150141	OILY WATER	2900	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YES
			!		8895 CALIFORNIA DRIVE	ENVIRONMENTAL			1,
					CASEYVILLE, IL 62232	UPW103665-IL			Į
1/19/2012	108438IL	9150143	OILY WATER	3000	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
			<u> </u>		CASEYVILLE, IL 62232				
1/19/2012	108438IL	9150145	OILY WATER	4525	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
					CASEYVILLE, IL 62232				
1/19/2012	108438IL	9150144	OIL WATER	2950	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			[
			<u> </u>		CASEYVILLE, IL 62232				
1/19/2012	108438IL	9150142	OILY WATER	2600	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
	l				8895 CALIFORNIA DRIVE	UPW103665-IL		1	1.23
					CASEYVILLE, IL 62232				
1/19/2012	108438IL	9150103	OILY WATER	4550	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL]	1.20
					CASEYVILLE, IL 62232				
1/19/2012	108438IL	9150000	OILY WATER	2780	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR00107086	FLY ASH	YES
	Į į				8895 CALIFORNIA DRIVE	UPW103665-IL			
	1		[CASEYVILLE, IL 62232				

1/20/2012	IF1002105S	9052007	SURFACTANT	2000	DIAL CORPORATION		T 1272.2		_ ;
1,20,2012	11-10021033	0033067	JUNFACIANI	1		IPS	9290019999	FLY ASH	YES
		ļ			6201 McKISSOCK	5108	3		
1/20/2012	44452411		5040		ST. LOUIS, MO 63147				[
1/20/2012	1112311	8853009	SOAP			IPS	9290019999	FLY ASH	YES
					6901 McKISSOCK	5108	3		ļ
					ST. LOUIS, MO 63147				
1/20/2012	108438IL	9150018	OILY WATER	4375	ILLINI ENVIRONMENTAL INC	†LLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
_					CASEYVILLE, IL 62232		<u> </u>	ļ	-
1/20/2012	109282IL	7119330	OIL WATER	4449	THE KIESEL COMPANY	THE KIESEL CO	9291897488	FLY ASH	YE:
			EMULSION		#1 BRANCH ST	UMP07715-IL			- 1
					ST. LOUIS, MO 63147	·			
1/20/2012	108438IL	9150009	OILY WATER	4400	ILLINI ENVIRONMENTAL INC	ILLINI	ILR000107086	FLY ASH	YES
					8895 CALIFORNIA DRIVE	UPW103665-IL			
			l	·	CASEYVILLE, IL 62232]	
1/23/2012 108	108438IL	9150008	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YΕ
					8895 CALIFORNIA DRIVE	UPW103665-IL			
ļ					CASEYVILLE, IL 62232]	t:	
1/23/2012	108438IL	9150005	OILY WATER	4297	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YE
					8895 CALIFORNIA DRIVE	UPW103665-IL	•		1
					CASEYVILLE, IL 62232				- 1
1/23/2012 10	108438IL	9150007	OILY WATER	2800	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YE
	1				8895 CALIFORNIA DRIVE	UPW103665-IL			
					CASEYVILLE, IL 62232			1	
1/23/2012	111531IL	8853003	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YE
	}				6901 McKISSOCK	510			
					ST. LOUIS, MO 63147				•
1/23/2012	108438IL	9150004	OILY WATER	2850	ILLINI ENVIRONMENTAL, INC	ILLINI	ILR000107086	FLY ASH	YE
:					8895 CALIFORNIA DRIVE	UPW103665-IL		1	
					CASEYVILLE, IL 62232				
1/24/2012	IF1002105S	8853088	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	I ELV ASH	YE
					6201 MCKISSOCK	510		71 21 7311	''
	İ				ST LOUIS, MO 63147		Ĭ		ĺ
1/24/2012	108438IL	9150006	OILY WATER	2875		IIIIIII	II P000107086	ELVACH	YE
, ,				2075			1511000107000	ויני אארו	'"
					į.			1	[
1/24/2012	111666IL	3552913	SEPARATOR	4040	 	HERITAGE	1630455221	I FI V ASH	Y
					*	1	103040322	1 5 73 11	"
	1					0. 110014400-4			
1/24/2017	10843811	9150003	LOUY WATER	2750		HILIMI	II P000107090	ELV ACU	YE
1/24/2012	111666IL	3552913	SEPARATOR SLUDGE OILY WATER	4040	ILLINI ENVIRONMENTAL, INC 8895 CALIFORNIE DRIVE CASEYVILLE, IL 62232 METRO/ED KRAMER 707 NO FIRST ST ST LOUIS, MO 63102 ILLINI ENVIRONMENTAL, INC	UPW103665-IL HERITAGE UPW0314460-4	1630455221 ILR000107086	FLY ASH FLY ASH	_ _

,		·			8895 CALIFORNIE DRIVE	UPW103665-IL			j
		<u> </u>			CASEYVILLE, IL 62232				ļ
1/24/2012	IF1002105S	885308	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6201 MCKISSOCK	5108			
					ST LOUIS, MO 63147				1
1/25/2012	111531 L	8853004	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6901 MCKISSOCK	5108			
					ST LOUIS, MO 63147				
1/25/2012 if1	if1002105s	8853090	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
			1		6201 MCKISSOCK	5108			
					ST LOUIS, MO 63147				
1/25/2012	111666IL	3552926	SEPARATOR	4040	METRO/ED KRAMER	HERITAGE	1630455221	FLY ASH	YES
			SLUDGE		707 N FIRST ST	UPW-0314460-OH			
					ST LOUIS, MO 63102	_]]
1/25/2012	111531il	853005	SOAP	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
	1				6901 MCKISSOCK	5108			
					ST LOUIS, MO 63147				
1/25/2012	IF1002105S	8853099	SURFACTANT	3000	DIAL CORPORATION	IPS	9290019999	FLY ASH	YES
					6201 MCKISSOCK	5108			
					ST LOUIS, MO 63147				
1/30/2012 1	109282il	7119336	OIL WATER	4421	THE KIESEL COMPANY	THE KIESEL CO	9291897488	FLY ASH	YES
	ł 1		EMULSION		#1 BRANCH ST	UMP07715-IL			
					ST. LOUIS, MO 63147				
1/30/2012	109282ii	7119337	OIL WATER		THE KIESEL COMPANY	THE KIESEL CO	9291897488	FLY ASH	YES
	1		EMULSION	4749	#1 BRANCH ST	UMP07715-IL			
					ST. LOUIS, MO 63147				

SOLIDIFICATION INFORMATION

DATE_		MANIFEST	WASTE NAME	GALLONS	GENERATOR NAME, ADDRESS, CITY, STATE, ZIP	HAULER & ID	GENERATOR ID	REAGNET OR ABSORBENT	PA PA
2/2/2012	109282IL	7119349	OIL WATER EMULSION		THE KIESEL COMPANY #1 BRANCH ST ST LOUIS, MO 63147	THE KIESEL CO. UMP07715-IL	9291897488		YES
2/3/2012	109282IL	7119350	OIL WATER EMULSION	4472	THE KIESEL COMPANY #1 BRANCH ST ST LOUIS, MO 63147	THE KIESEL CO. UMP07715-IL	9291897488	FLY ASH	YES
2/7/2012	109282IL	7119357	OILY WATER EMULSION	4497	THE KIESEL COMPANY #1 BRANCH ST ST LOUIS, MO 63147	THE KIESEL CO. UMP07715-IL	9291897488	FLY ASH	YES
2/8/2012	109282IL	7119356	OIL WATER EMULSION	4546	THE KIESEL COMPANY #1 BRANCH ST ST LOUIS, MO 63147	THE KIESEL CO. UMP07715-IL	9291897488	FLY ASH	YES
				_					
]

A S	designed for use on elite (12-pitch typer 1. Generator ID Number ILRO0000009990		of 3 Emergency Response Phone	4. Manifest Tr	acking nun		_
5.Generator Name and 1135 NORTH DU QUOIN, 1	MAPLE	Jedry Mrzo	Generators Site Address profifer 1135 INDUSTRIAL DU QUOIN, IL 52	PARK BLV		2012	•
Generator's Phone 6. Transporter 1 Companion A STE MANA				U.S. EPA ID Nu	mber ů ő ű	9 9 9 9	0 6
7. Transporter 2 Compan	ry Name			U.S. EPA ID Nu		· · · · · · · · · · · · · · · · · · ·	
8. Designated Facility Na COTTON WOOD 10490 HILLS	me and Site Address HILLS RDF TOWN ROAD B			U.S. EPA ID Nu		0226	
MARISSA, II. Facility's Phone: 9a. 9b. U.S. DOT Descrip	r 62257 otion (including Proper Shipping Name, Ha	azard Class, ID Number.		10. Conta		11. Total	12. (
HM and Packing Group (• 	No.	Туре	Quantity	WŁA
1695539	GULATED MATERIAL, 169-5	5539 FIVTER SLU	DGE,		см	20	YE
2. 							
3.							
4.					.		
manked and tabeled/place	OR'S CERTIFICATION: Thereby declare that the anded, and are in all respects in proper condition contents of this consignment conform to the temperature.	on for transport according to ap	oplicable international and national govern	e by the proper shippi mental regulations. If	nç name, an export shipn	d are classified, pa nent and I am the I	ickaged Primary
Generator's/Offeror's Prints	•	Sign	ature	Fina		Month Day	Yea
16. International Shipment	s ☐ Import to U.S.	Export from	Port of entry/exit:	Tur 4		DOIO	1/O
Transporter signature (for e		· ·	Date leaving U.S.:	· · · · · · · · · · · · · · · · · · ·		,	
Transporter i Printed/Typer	gement of Receipt of Materials d Name On D. enner	Signi	mure) ,	1		Month Day	Yea / Z
Transporter 1 Printed/Typed Transporter 2 Printed/Typed		Signa	ature + LAMEN	·		Month Day	Year
18. Discrepancy						<u> </u>	<u> </u>
18a. Discrepancy Indication	Space Quantity	□ Type	Residue Manifest Reference Nu	□ Partial Rej	ection	□Full Rej	ection
18b. Alternate Facility (or G	enerator)		manifest territories in	U.S. EPA II) Number		
Contibute Phone	•				 	Month Day	Year
Facility's Phone 18c. Signature of Alternate	Facility (or Generator)				1	1	l
		3		4.	1		<u> </u>
	Codes)		nanifest except as noted in Item 18a			Month 1 Day 1	

Couch, Kendall

From:

Dennison, Denny <ddenniso@wm.com>

Sent:

Thursday, June 14, 2012 10:35 PM

To:

Couch, Kendall

Subject:

RE: Cottonwood Hills

Yes the isopach contours do make the elevation contours somewhat cluttered ... It looks like the typical plateau elevation was approx 520 ft msl and the peak was approx 530 ft msl as of the end of March (when the survey performed) ... we will be surveying again at end of June

From: Couch, Kendall [mailto:Kendall.Couch@Illinois.gov]

Sent: Thursday, June 14, 2012 4:20 PM

To: Dennison, Denny

Subject: RE: Cottonwood Hills

Tried to figure out an approximate elevation for the top of the landfill from the volume calculation diagram, but couldn't do it. Could you rap with James and give me an approximate elevation for the highest point on the landfill? Thanks

From: Dennison, Denny [mailto:ddenniso@wm.com]

Sent: Thursday, June 14, 2012 3:55 PM

To: Couch, Kendall

Cc: Durako, Joe; Raynor, Bill Subject: RE: Cottonwood Hills

We survey the landfill every quarter at the end of the month Ie March 31, June 30, etc They may have been performing the annual survey monument check as required per the regs or possibly were staking out the final cover limits to be constructed this year I have attached the March 30 survey surface (shows elevations) and the annual inspection letter

From: Couch, Kendall [mailto:Kendall.Couch@Illinois.gov]

Sent: Thursday, June 14, 2012 2:26 PM

To: Dennison, Denny **Subject:** Cottonwood Hills

Denny

I'm writing up the inspection report for my May 24 inspection. I think Hurst-Rosche was out at the landfill performing a survey a day or two prior. Could you find out what the elevation for the landfill was on that day or latest elevation recorded by Hurst-Rosche?

Thanks Kendall

Kendall Couch

Illinois Environmental Protection Agency Bureau of Land 2009 Mall Street Collinsville, Illinois 62234

kendall.couch@illinois.gov Website: <u>Click Here</u>

1

Couch, Kendall

From:

Dennison, Denny <ddenniso@wm.com>

Sent:

Thursday, June 14, 2012 3:55 PM

To:

Couch, Kendall

Cc: Subject:

Durako, Joe; Raynor, Bill RE: Cottonwood Hills

Attachments:

Cottonwood Quarterly Volume Calcs 2012 1Q.pdf; Survey Control Monuments 2012

05-25-12 Cottonwood.pdf

We survey the landfill every quarter at the end of the month le March 31, June 30, etc They may have been performing the annual survey monument check as required per the regs or possibly were staking out the final cover limits to be constructed this year I have attached the March 30 survey surface (shows elevations) and the annual inspection letter

From: Couch, Kendall [mailto:Kendall,Couch@Illinois.gov]

Sent: Thursday, June 14, 2012 2:26 PM

To: Dennison, Denny Subject: Cottonwood Hills

Denny

I'm writing up the inspection report for my May 24 inspection. I think Hurst-Rosche was out at the landfill performing a survey a day or two prior. Could you find out what the elevation for the landfill was on that day or latest elevation recorded by Hurst-Rosche?

Thanks Kendáll

Kendall Couch

Illinois Environmental Protection Agency Bureau of Land 2009 Mall Street Collinsville, Illinois 62234 Phone: 618/346-5141 FAX: 618/346-5155

kendall.couch@illingis.gov Website: Click Here



Please consider the environment before printing this e-mail

Waste Management recycles enough paper every year to save 41 million trees. Please recycle any printed emails.



No. 5 Bank Square East St. Louis, IL 62203 Telephone: 618-398-0890 Facsimile: 618-398-1339 Email: esl@hurst-rosche.com

www.hurst-rosche.com



Hillsboro, Illinois Marion, Illinois Springfield, Illinois Bamhart, Missouri Neosho, Missouri May 25, 2012

Mr. Ernest H. Dennison, P.E. Waste Management of Illinois 601 Madison Road East St. Louis, Illinois 62201

SUBJECT: Control Survey Check

Cottonwood Hills Recycling & Disposal Facility

Waste Management of Illinois

Dear Mr. Dennison:

As requested, we have inspected the survey control and monuments at the Cottonwood Hills Recycling and Disposal Facility. The inspection was conducted on May 21, 2012. In our opinion the monuments and their identifying signs are in good condition and in sufficient number to maintain the horizontal and vertical control system at the facility.

If you should have any questions or require additional information, please feel free to contact our office.

Sincerely,

HURST-ROSCHE ENGINEERS, INC.

James W. Roth, PLS

JWR/jc

